



Hartzell
HC-E4N-5B
MANUFACTURED 8/26/99
Installed on AC: 10/25/05

N441MT
 Prop S/N: **HE211**
Position 1
Aspen Flight Operations LLC

Total Time: **1,894.1**
 Last Overhaul: **10/25/05**
 Time Since Overhaul: **195.6**
 A/C Hours @ Install: **6,558.50**

Projection Period

Hours:	0.0
Cycles:	0
Calendar:	0,

Due	Event	Event description	Frequency	Last Compliance	Next Compliance Due	Remaining	Comments
*	M HC-610001	Propeller 400 Hour Inspection	400 hrs/12 Month(s)	1,894.1 hrs 11/7/2006	2,294.1 hrs 11/7/2007	400.0 hrs 359 days	
*	M HC-610100	Propeller Overhaul, 4-Blade Aluminum Hub	4,000 hrs/72 Month(s)	1,698.5 hrs 10/21/2005	5,698.5 hrs 10/21/2011	3804.4 hrs 1803 days	
*	M AD 2005-14-11	Propellers Returned to Service by Southern California Propeller Service VXS617L		4,850.0 hrs 10/21/2005			N/A per overhaul location

**** End of Report ****

" * " Indicates that the item has been researched

Note: This report is provided for planning purposes only and does not supplement or replace the official log books.